



**RESUME WORK NOTICE
IN THE MATTER OF THE NATIONAL ENERGY BOARD ACT,
FOLLOWING AN ORDER UNDER SECTION 51.1**

The undersigned National Energy Board Inspection Officer hereby notifies

TransCanada Pipelines Limited (TCPL)

_____ that the hazardous or detrimental situation
Company Representative and company name

described in Order No. GC-001-2016 has been remedied to the satisfaction of the Inspection Officer.
Inspection Officer order

Therefore, Suspended work may resume, and/or
 the measures specified in the order have been satisfied.

Dated: 23 November 2016

Inspection Officer	_____	1950	_____
	Name	IO Designation #	Telephone
	23 November 2016	_____	
	Date	Signature	
Centre 10 – 517, 10th Avenue SW Calgary AB T2R 0A8			